



[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-3637; Directorate Identifier 2014-NM-219-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model MD-11 and MD-11F airplanes. This proposed AD was prompted by a report of fuel odor in the cabin. Fuel was found leaking from a cracked fuel line shroud in the left cargo compartment equipment tunnel. This proposed AD would require a check for the presence of fuel at the fuel shroud drain; a high frequency eddy current (HFEC) inspection for cracked fuel line shrouds; a pressure test of the drain system of the tail tank fuel shroud and a pressure test of the drain system of the aft fuselage fuel shroud to determine cracking; and corrective actions, if necessary. We are proposing this AD to detect and correct fuel leaking from a cracked fuel line shroud, which could result in fuel accumulation below the cargo compartment floor and consequent increased risk of fire.

DATES: We must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- Fax: 202-493-2251.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3637.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3637; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Philip Kush, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office (ACO),

3960 Paramount Boulevard, Lakewood, CA 90712-4137; telephone: 562-627-5263; fax: 562-627-5210; email: Philip.Kush@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA-2015-3637; Directorate Identifier 2014-NM-219-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of fuel odor in the cabin. Fuel was found leaking from a cracked fuel line shroud in the left cargo compartment equipment tunnel. This condition, if not corrected, could result in fuel accumulation below the cargo compartment floor and consequent increased risk of fire.

Related Service Information under 1 CFR part 51

We reviewed Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014. The service information describes procedures for checking for the presence of fuel at the fuel shroud drain; a HFEC inspection for cracked fuel line shrouds; a pressure test of the drain system of the tail tank fuel shroud and a pressure test of the drain system of the aft fuselage fuel shroud to determine cracking; and corrective actions. This service

information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of this NPRM.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 90 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

Estimated costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Check for presence of fuel at the fuel shroud drain	2 work-hours X \$85 per hour = \$170, per inspection cycle	\$0	\$170, per inspection cycle	\$15,300, per inspection cycle
HFEC Inspection (optional)	5 work-hours X \$85 per hour = \$425, per inspection cycle	\$0	\$425, per inspection cycle	\$38,250, per inspection cycle
Pressure Test	3 work-hours X \$85 per hour = \$255, per inspection cycle	\$0	\$255, per inspection cycle	\$22,950, per inspection cycle

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2015-3637; Directorate Identifier 2014-NM-219-AD.

(a) Comments Due Date

We must receive comments by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model MD-11 and MD-11F airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel System.

(e) Unsafe Condition

This AD was prompted by a report of fuel odor in the cabin. Fuel was found leaking from a cracked fuel line shroud in the left cargo compartment equipment tunnel. We are issuing this AD to detect and correct fuel leaking from a cracked fuel line shroud,

which could result in fuel accumulation below the cargo compartment floor and consequent increased risk of fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Check, Inspection, Test, and Corrective Actions

Do the actions in paragraphs (g)(1) or (g)(2) of this AD, as applicable.

(1) Except as specified in paragraph (h) of this AD: At the applicable time in Table 1 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014, do the actions in paragraphs (g)(1)(i), (g)(1)(ii), and (g)(1)(iii) of this AD. Before further flight do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014. Repeat the actions thereafter at the applicable time in Table 1 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014.

(i) Check for the presence of fuel at the fuel shroud drain.

(ii) Do a high frequency eddy current (HFEC) inspection for cracked fuel line shrouds.

(iii) Do a pressure test of the drain system of the tail tank fuel shroud and a pressure test of the drain system of the aft fuselage fuel shroud to determine if there is cracking.

(2) Except as specified in paragraph (h) of this AD: At the applicable time in Table 2 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014, do the actions in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD. Before further flight do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014. Repeat the actions thereafter at the applicable

time in Table 2 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014.

(i) Check for the presence of fuel at the fuel shroud drain.

(ii) Do a pressure test of the drain system of the tail tank fuel shroud and a pressure test of the drain system of the aft fuselage fuel shroud to determine if there is cracking.

(h) Exception to the Service Information

Where Boeing Alert Service Bulletin MD11-28A148, dated August 29, 2014, specifies a compliance time of “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to:

9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Philip Kush, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification

Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; telephone: 562-627-5263; fax: 562-627-5210; email: Philip.Kush@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on September 17, 2015.

John P. Piccola,
Acting Manager,
Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2015-24565 Filed: 9/28/2015 08:45 am; Publication Date: 9/29/2015]